

Transmittance Characteristics of U.S. Army Rotary-Wing Aircraft Transparencies

By

Sean L. Wentworth **Everette McGowin III** Rebecca H. Ivey Clarence E. Rash William E. McLean



Aircrew Health and Performance Division

March 1995

DTIC QUALITY INSPERIENCE 3

Approved for public release; distribution unlimited.

United States Army Aeromedical Research Laboratory Fort Rucker, Alabama 36362-0577

Notice

<u>Qualified</u> requesters

Qualified requesters may obtain copies from the Defense Technical Information Center (DTIC), Cameron Station, Alexandria, Virginia 22314. Orders will be expedited if placed through the librarian or other person designated to request documents from DTIC.

Change of address

Organizations receiving reports from the U.S. Army Aeromedical Research Laboratory on automatic mailing lists should confirm correct address when corresponding about laboratory reports.

Disposition

Destroy this document when it is no longer needed. Do not return it to the originator.

Disclaimer

The views, opinions, and/or findings contained in this report are those of the author(s) and should not be construed as an official Department of the Army position, policy, or decision, unless so designated by other official documentation. Citation of trade names in this report does not constitute an official Department of the Army endorsement or approval of the use of such commercial items.

Human use

Human subjects participated in these studies after giving their free and informed voluntary consent. Investigators adhered to AR 70-25 and USAMRDC Reg 70-25 on Use of Volunteers in Research.

Reviewed:

RI¢HARD R. LĒ

Director, Aircrew Health and

Performance Division

Released for publication:

EY, **0**.D., Ph.D.

Chairman, Scientific Review Committee DENNIS F. SHANAHAN Colonel, MC, MFS

Commanding


REPORT DOCUMENTATION PAGE								Form Approved OMB No. 0704-0188				
1a. REPORTS Unclass	SECURITY CLAS	SIFICATION	1		1b. RESTRICTIVE MARKINGS							
2a. SECURITY	CLASSIFICATIO	N AUTHOF	RITY		3. DISTRIBUTION/AVAILABILITY OF REPORT Approved for public release, distribution unlimited							
2b. DECLASS	FICATION / DOV	VNGRADING	G SCHEDULE									
	NG ORGANIZATI Report No				5. MONITORING ORGANIZATION REPORT NUMBER(S)							
U.S. Ar	PERFORMING O my Aerome h Laborat	dical	ION	6b. OFFICE SYMBOL (If applicable) MCMR – UAD	7a. NAME OF MONITORING ORGANIZATION U.S. Army Medical Research and Materiel Command							
P.O. Bo	(City, State, and ax 620577 cker, AL		-0577		7b. ADDRESS (City, State, and ZIP Code) Fort Detrick Frederick, MD 21702-5012							
8a. NAME OF ORGANIZA	FUNDING / SPO TION	NSORING		8b. OFFICE SYMBOL (If applicable)	9. PROCUREME	NT INSTRUMENT IDENTIFIC	ATION NU	UMBER				
8c. ADDRESS	(City, State, and	ZIP Code)			10. SOURCE OF I	FUNDING NUMBERS						
	1-19, -1-1-, -11-1	,			PROGRAM ELEMENT NO.	PROJECT NO.	TASK NO.	WORK UNIT ACCESSION NO.				
					0602787A	3M162787AA879	PE	164				
(U) Tra	L AUTHOR(S)	e Char				ng Aircraft Tra						
13a. TYPE OF Final	REPORT		13b. TIME CO FROM	OVERED TO	14. DATE OF RE 1995 Marc	PORT <i>(Year, Month, Day)</i> ch	15. PAG	GE COUNT 29				
16. SUPPLEMI	ENTAL NOTATIO	N										
17.	COSATI CO	DES				necessary and identify by bloo)				
FIELD	GROUP	SUB	-GROUP	Windscreen, t	ransparency	, optical testi	.ng					
13 14	06 04											
19. ABSTRACT (Continue on reverse if necessary and identify by block number) This report documents a survey of the spectral and luminous transmittance characteristics of transparencies (windscreens) used in currently fielded U.S. Army rotary-wing aircraft. The survey was conducted in two phases. In the first phase, samples of windscreens from each aircraft type were evaluated in the laboratory for phototopic (day) and scotopic (night) luminous transmittance. The spectral transmittance of each sample also was measured. Based on laboratory measurements of unused samples, all windscreens met specifications. However, field measurements on windscreens showed consistent failure of luminous transmittance requirements. This loss of transmittance is attributed to haze resulting from exposure to environmental factors.												
	TON / AVAILABIL		STRACT SAME AS RPT	T. DTIC USERS	21. ABSTRACT S Unclassif	ECURITY CLASSIFICATION						
22a. NAME OF	RESPONSIBLE Science S	INDIVIDUAI	L		22b. TELEPHONE (Include Area Code) 22c. OFFICE SYMBOL (334) 255-6907 MCMR-UAX-SS							

Table of contents

÷										ŀ	aç	Jе	no	ο.
List	of tables			•										2
Intro	duction													3
Speci	fications and requirements	s.												3
Metho	dology												•	9
1	Spectral transmittance													9
:	Luminance transmittance												1	LO
;	Field measurements												1	LO
Data													1	LO
	Spectral transmittance .									•			1	LO
1:	Luminous transmittance .												1	L 9
Summa	су			•					•				2	23
Refer	ences						•		•				2	24
Append	dix A - List of transpare	ncy	man	ufa	cti	ıreı	ŝ						2	26
Append	dix B - List of equipment	man	ufa	ctu	rei	cs						•	2	29
	<u> List</u>	of f	iqu	res	<u>.</u>									
Figure	e no.									F	aç	је	nc	٥.
1.	The AH-1 Cobra			•										4
2.	The AH-64 Apache													4
3.	The CH-47D Chinook			•										5
4.	The OH-6 Cayuse													5
5.	The OH-58A Kiowa			•										6
6.	The OH-58C Kiowa													6
7.	The OH-58D Kiowa													7

<u>List of figures</u> (Continued).

Figure	no.	Ρā	ıge	no.
8.	The TH-67 Creek		•	. 7
9.	The UH-1 Iroquois			. 8
10.	The UH-60 Black Hawk			. 8
11.	Spectral transmittance curve for AH-1 Cobra			11
12.	Spectral transmittance curve for AH-64 Apache			12
13.	Spectral transmittance curve for CH-47D Chinook			13
14.	Spectral transmittance curve for OH-58A/D Kiowa			14
15.	Spectral transmittance curve for OH-58C Kiowa			15
16.	Spectral transmittance curve for TH-67 Creek			16
17.	Spectral transmittance curve for UH-1 Iroquois			17
18.	Spectral transmittance curve for UH-60 Black Hawk			18
19.	Example of surface abrasion present in an AH-64 windscreen			23
	<u>List of tables</u>			
Table n	0.	Pa	ge	no.
1.	Luminous transmittance (in percent)	•	•	20
2.	Field measurements of photopic luminous transmitta (in percent)	nc	e	21
3.	Comparison of laboratory and field photopic lumino transmittance measurements	us •		22



Introduction

This report documents a survey of the spectral and luminous transmittance characteristics of transparencies (windscreens) used in currently fielded U.S. Army rotary-wing aircraft (AH-1 Cobra, AH-64 Apache, CH-47 Chinook, OH-6 Cayuse, OH-58A/C/D Kiowa, TH-67 Creek, UH-1 Iroquois, and UH-60 Black Hawk [Figures 1-10]). These characteristics are essential to addressing issues related to aviator and crewman visual performance. In addition, spectral transmittance characteristics impact the performance of helmet-mounted imaging systems, such as the AN/AVS-6 Aviator's Night Vision Imaging System (ANVIS).

Previous investigations of the optical characteristics of U.S. Army rotary-wing aircraft transparencies (Chiou, 1975, 1976; Chiou, Park, and Moser, 1976; Crosley, 1968) may no longer be representative of currently fielded transparencies. Manufacturers of U.S. Army aircraft transparencies often change with each procurement contract. Appendix A provides a list of current manufacturers.

The survey was conducted in two phases. In the first phase, samples of windscreens from each aircraft type were evaluated in the laboratory for photopic (day) and scotopic (night) luminous transmittance. The spectral transmittance of each sample also was measured.

Installed transparencies are exposed continuously to the environment, collision with airborne particulate matter, and the abuses which often accompany aircraft maintenance. Therefore, to provide a more realistic assessment of transmittance values as experienced in the field, a second phase consisting of field measurements of photopic luminous transmittance for windscreens installed on aircraft on the flight line was conducted.

The laboratory measurements were taken on new (or not previously used) transparency samples. Due to limited availability of such transparencies, only a single sample of each forward windscreen could be obtained for each aircraft type. [An exception to this was the inability to obtain any front windscreens of the OH-6 or the right front windscreen for the UH-60.] Therefore, the data reported herein should be considered only representative of transparency performance. Field measurements (photopic transmittance only) were made on six aircraft per type.

Specifications and requirements

MIL-W-81752A(AS), "Military specification: Windshield systems, fixed wing aircraft, general specification for,"



Figure 1. The AH-1 Cobra.



Figure 2. The AH-64 Apache.



Figure 3. The CH-47D Chinook.



Figure 4. The OH-6 Cayuse.



Figure 5. The OH-58A Kiowa.



Figure 6. The OH-58C Kiowa.



Figure 7. The OH-58D Kiowa.



Figure 8. The TH-67 Creek.



Figure 9. The UH-1 Iroquois.



Figure 10. The UH-60 Black Hawk.

requires attack type aircraft to have an average luminous transmittance of not less than 80 percent when measured at normal angles of incidence to the surface. Other aircraft are required to have an average luminous transmittance of not less than 60 percent when measured at normal angles of incidence to the surface.

During day flights, pilotage and other external tasks are primarily accomplished by naked eye viewing through the windscreens and windows. However, current U.S. Army doctrine requires pilots and crewmen to perform missions successfully during periods of low illuminance, e.g., at night and in foul weather. To achieve acceptable performance under these conditions, devices based on the principle of image intensification are used in the cockpit and crew areas. The most prominent of these devices is the ANVIS. This night vision system has a spectral response of 450-950 nanometers (nm) with an enhanced sensitivity from 625-900 nm (MIL-L-85762A). Windscreens and windows must provide adequate spectral transmittance over this latter spectral range to optimize ANVIS performance.

 $\texttt{MIL-W-81752A}\,(\texttt{AS})$ states the windshield shall be (ANVIS) compatible over the wavelength range of 600-900 nanometers.

Methodology

Spectral transmittance

Spectral transmittance data were obtained in a darkened laboratory using an EG&G Gamma Scientific* model C-9 spectral scanning system and a model RS-1 tungsten source. Spectroradiometric data were measured over the wavelength range of 350-950 nanometers in 5-nm steps for the reference tungsten source alone and for each transparency sample/source combination. The transmittance curves were obtained by performing a division, by wavelength, of the transparency/source combination data by the source data.

A sample of the left front windscreen was measured in each aircraft with side-by-side seating. A lower front windscreen sample was measured for the attack aircraft, which have tandem seating. In order to minimize scratching of the unused transparencies during measurement, the protective sheeting was removed from as small an area as possible. Therefore, measurements were taken at arbitrary and different points on each samples. [Note: This was not considered to be a relevant factor since an investigation of several samples showed a variation of less than 5 percent across the sample. A similar investigation

^{*}See Appendix B.

of the effect of slant (deviation from normal) also showed a variation of less than 5 percent.] Settings of 900 volts photomultiplier tube anode voltage and 1-degree aperture size on the collection optics were used.

Luminous transmittance

Photopic and scotopic luminous transmittance values were measured in a darkened laboratory using a Photo Research* model 1980A photometer and EG&G Gamma Scientific model RS-1 tungsten source. Following a prescribed warm-up period for the photometer and the reference lamp, luminous transmittance measurements were taken for each sample using the photopic and scotopic filters integral to the photometer. Each measurement consisted of reading the luminance of the reference lamp, placing the respective transparency sample normal to the optical path, and taking a second luminance reading. The transmittance was calculated by dividing the luminance value obtained of the sample/source combination by the value obtained of the source alone. Three readings were obtained for each sample. The mean of these three values was calculated and reported.


Field measurements

Field measurements of photopic transmittance values were acquired for six of each aircraft type on flight lines at U.S. Army airfields at Fort Rucker, Alabama. [Note: An exception was the OH-58C aircraft, where only four aircraft were measured.] Measurements were made using an EG&G Gamma RS-1 tungsten source powered by a field generator and a Minolta* 1-degree aperture luminance meter. Each measurement consisted of reading the luminance of the reference source alone and reading the reference source luminance from a position of the left seat for aircraft with side-by-side seating and from the front seat of aircraft with tandem seating. The transmittance was calculated by dividing the value obtained from the cockpit by the value of the source alone.


<u>Data</u>

Spectral transmittance


The transmittance curves for the windscreen sample are provided in Figures 11-18. The samples from AH-64 (except aft windscreen), CH-47, UH-1, and UH-60 aircraft were of glass composition. The AH-1, OH-58A/C/D, and TH-67 samples were of acrylic composition. All samples were of "clear" material except for the TH-67, which had a bluish tint.




Spectral transmittance curve for AH-1 Cobra. Figure 11.




Spectral transmittance curve for AH-64 Apache. Figure 12.




Spectral transmittance curve for CH-47D Chinook. Figure 13.




Spectral transmittance curve for OH-58A/D Kiowa. Figure 14.




Spectral transmittance curve for OH-58C Kiowa. Figure 15.



Spectral transmittance curve for TH-67 Creek. Figure 16.



Spectral transmittance curve for UH-1 Iroquois. Figure 17.



Spectral transmittance curve for UH-60 Black Hawk. Figure 18.

The spectral curves in Figures 11-18 correspond to the descriptions above. The curves for the AH-1, OH-58, and TH-67 samples demonstrate the spectral transmittance characteristics of acrylic materials. These include an ultraviolet cut-off between 350-380 nm and excellent spectral neutrality (flatness of transmittance) over the visible spectral range 400-780 nm. These acrylic windscreens also provide high, relatively flat, transmittance over the spectral response range of the ANVIS, 450-930 nm. The TH-67 sample has a deviation from neutrality over the range 560-780 nm (Figure 16). This decrease in transmittance of the red wavelengths produces the bluish color of the tint.

The glass samples of the AH-64, CH-47, UH-1, and UH-60 also provide a relatively neutral transmittance over the measured spectral range with a similar UV cutoff around 360 nm, but present some relative falloff in transmittance beyond 600 nm. This is of little significance to naked eye vision, which peaks at 550 nm. It also has little effect on ANVIS performance, which has enhanced sensitivity over the spectral range of 625-900 nm.

Note 1: The OH-6, while not available for laboratory measurement of spectral transmittance, is manufactured from acrylic material and should have optical characteristics similar to the AH-1, OH-58A, and TH-67 samples.

Note 2: The apparent increase of transmittance below 360 nm present in the curves is an artifact of the collection optics and spectral sensitivity of the spectroradiometer.

Luminous transmittance

Clear glass materials typically provide 80 to 92 percent photopic luminous transmittance; acrylic typically provides 85 to 92 percent (IES, 1984). The photopic and scotopic luminous values obtained in the laboratory measurements are presented in Table 1. The photopic values ranged from 73 to 93 percent; scotopic values ranged from 81 to 91 percent. When the TH-67 tinted samples are excluded, the photopic values for the glass samples ranged from 82 to 88 percent and the values for the acrylic samples ranged from 90 to 93 percent. The lowest photopic values, 73 and 77 percent, were for the tinted TH-67 samples.

The scotopic values generally tracked within a few percentage points of their corresponding photopic values. This was due to the flatness of the transmittance properties of glass and acrylic. The exception, as noted, of the TH-67 samples and their attenuation of red light produced higher scotopic values.

Based on the laboratory measurements, all of the tested windscreen samples met the requirements of MIL-W-81752A(AS).

The photopic luminous transmittance values obtained for flight line aircraft are presented in Table 2. These values ranged from 58 to 84 percent.

Table 1.

Luminous transmittance (in percent).

Aircraft	Panel po	sition and FSN*	Photopic	Scotopic		
AH-1	front	1560-01-028-0476	92	91		
AH-64	forward	1560-01-170-7475	82	81		
AH-64	center	1560-01-170-7474	82	81		
AH-64	aft	1560-01-165-9621	88	89		
CH-47	right	1560-00-133-7158	83	82		
CH-47	center	1560-00-113-7857	85	87		
CH-47	left	1560-00-133-7157	82	82		
OH-6	left right	1560-00-133-6186 1560-00-133-6229	**	**		
OH-58A	right	1560-00-127-3179	90	91		
OH-58A	left	1560-00-127-3181	92	91		
OH-58C OH-58C (curved)	right left	1560-01-070-5360 1560-01-070-5359	92 92	91 91		
OH-58D	right	1560-00-127-3179	90	91		
OH-58D	left	1560-00-127-3181	92	91		
TH-67	right	206-031-115-105	73	82		
TH-67	left	206-031-115-0335	77	85		
UH-1	right	1560-00-433-7271	89	89		
UH-1	left	1560-00-433-7321	93	89		
UH-60	right	1560-01-084-2250	**	**		
UH-60	center	1560-01-207-7485	82	82		
UH-60	left	1560-01-084-2249	84	81		

^{*} Federal stock number; for TH-67, manufacturer part number is given.

^{**} Samples of OH-6 and OH-58 flat windscreens and the right front UH-60 windscreen were not available.

Table 2. Field measurements of photopic luminous transmittance (in percent).

Aircraft windscreen	Photopic transmittances (in percent)	Mean	Standard deviation
AH-1 front bottom	83, 75, 76, 81, 77, 82	79	3.4
AH-64 front bottom	71, 67, 76, 72, 73, 70	72	3.0
CH-47 front left	, 62, 68, 70, 63, 48*	66	3.9
OH-6 front left	80, 70, 67, 70, 71, 75	72	4.6
OH-58A front left	77, 77, 75, 78, 76, 75	76	1.2
OH-58C curved front left	53, 62, 59, 58*	58	3.7
OH-58C flat front left	70, 60, 58, 63, 58, 66	63	4.8
OH-58D front left	71, 72, 73, 74, 70, 76	73	2.2
TH-67 front left	65, 64, 62, 64, 63, 67	64	1.7
UH-1 front left	83, 86, 84, 82, 84, 84	84	1.3
UH-60 front left	5, 75, 75, 71, 74, 75	74	1.6

^{*} Note: For the CH-47, the first reading was invalid due to a recording error and for the last reading, condensation on the interior of windscreen produced an erroneous value; neither value is shown in the table. For the OH-58C with curved windscreen, only four aircraft were available for measurement. These windscreens exhibited significant levels of abrasion and the obtained values were further affected by condensation and fogging.

In Table 3, a comparison between the laboratory and field photopic luminous transmittance values (for front left windscreens) is presented. The percent decrease in photopic transmittance between the unused and fielded windscreens are presented in the last column. In each case, the field value decreased from the laboratory value. Percent decrease

Table 3.

Comparison of laboratory and field photopic luminous transmittance measurements.

Aircraft	Laboratory value	Field value	Percent decrease				
AH-1	92	79	14				
AH-64	82	72	12				
CH-47	83	66	20				
OH-6		72					
OH-58A	92	76	17				
OH-58C curved	92	58	37				
OH-58C flat		63					
OH-58D	92	73	21				
TH-67	77	64	17				
UH-1	93	84	10				
UH-60	84	74	12				

Note: Unused samples of OH-6 and OH-58C flat windscreens were not available.

ranged from 10 percent for the UH-1 to 37 percent for the OH-58C (curved). The mean percent decrease was 18 percent. (If the relatively large percent decrease value of 37 for the OH-58C is excluded, the mean percent decrease was 15 percent.) Several factors attributed to this decrease. As would be expected under field conditions, the windscreens were dirty both inside and outside. In addition, because the field measurements were

taken at night, condensation and fogging also were present in varying degrees. These factors, while contributing, are considered secondary to the effects of haze resulting from the highly abraded external surfaces of the windscreens. Figure 19 shows an example of an AH-64 windscreen having a significant level of abrasion.

Summary

All of the windscreen samples (except for the tinted TH-67) were found to be spectrally neutral over the visible spectrum. Likewise, all samples indicated sufficient spectral transmittance over the spectral range required for optimal performance of ANVIS.

For luminous transmittance, all of the unused samples measured in the laboratory met the requirements of MIL-W-81752A(AS). However, an analysis of the field measurements of



Figure 19. Example of surface abrasion present in an AH-64 wind-screen.

luminous transmittance, while qualified by the small sample size, shows significant decreases in transmittance for all windscreen types. These decreases are considered to be caused by haze resulting from the physical abuse to which the windscreens are subjected.

The governing specifications require attack aircraft to have an average luminous transmittance of not less than 80 percent and nonattack aircraft to have not less than 60 percent. All windscreen samples met this requirement in the laboratory measurements. However, based on field measurements, neither attack aircraft, the AH-1 or AH-64, met the 80 percent requirement. The OH-58C curved windscreens, with a mean value of 58 percent, failed to meet the 60 percent requirement for nonattack aircraft. The conclusion which can be drawn from this study seems to be that all windscreen samples meet the specification for luminous transmittance upon delivery, but during usage degrade in performance. Since data were not available to correlate performance degradation with length of service, it is not possible to formulate a recommendation on how often to replace the windscreens. However, it is obvious from the data that in the harsh environments of military flight, the optical performance of the windscreens does degrade below that required by the specification and this situation warrants a policy of closer inspection at the unit level.

References

- Chiou, W. C. 1975. <u>Visible spectral transmission characteristics of windscreens in Army aircraft</u>. Fort Rucker, AL: U.S. Army Aeromedical Research Laboratory. USAARL LR-75-29-7-8
- Chiou, W. C. 1976. <u>Visible and near infrared spectral</u> <u>transmission characteristics of windscreens in Army aircraft</u>. Fort Rucker, AL: U.S. Army Aeromedical Research Laboratory. USAARL Report 76-14.
- Chiou, W. C., Park, C. K., and Moser, C. E. 1976. <u>Attenuation of light transmission in Army aircraft transparencies due to slating</u>. Fort Rucker, AL: U.S. Army Aeromedical Research Laboratory. USAARL Report 76-23
- Crosley, J. K. 1968. <u>Tinted windscreens in U.S. Army</u>
 <u>aircraft</u>. Fort Rucker, AL: U.S. Army Aeromedical Research
 Laboratory. USAARU Report No. 68-7
- Department of Defense. 1988. <u>Military specification: Lighting, aircraft, interior, night vision imaging system compatible</u>. Washington, DC: Department of Defense. MIL-L-85762A.

- Department of Defense. 1988. <u>Military specification: Windshield systems, fixed wing aircraft, general specification for.</u>
 Washington, DC: Department of Defense. MIL-W-81752A(AS),
 Amendment 1.
- Illuminating Engineering Society (IES) of North America. 1984.

 <u>IES lighting handbook</u>. J. E. Kaufman, editor. New York, NY:

 IES of North America.

Appendix A

List of transparency manufacturers.

<u>AH-1</u>

Bell Helicopter Textron, Inc. 600 E Hurst Blvd. P.O. Box 482 Fort Worth, TX 76101-8020 (817)280-2011

LP Aero Plastics Inc. Road 1 P.O. Box B Jeannette, PA 15644-9730 (412)744-4448

AH-64

McDonald Douglas Helicopter Co. Sub of McDonald Douglas Corp. 6775 Centinela Ave. Culver City, CA 90230-6370 (310)305-6562

PPG Aircraft Product Sales 1719 Highway 72E P.O. Box 040004 Huntsville, AL 35804 (205)851-7001

CH-47

PPG Aircraft Product Sales 1719 Highway 72E P.O. Box 2200 Huntsville, AL 35804 (205)859-2500

Boeing Helicopter Division of the Boeing Co. Boeing Center Industrial Hwy Bldg 3-25 Ridley Park, PA 19078 (215)591-3010

Appendix A (Continued)

List of transparency manufacturers

OH-6

McDonnell Douglas Helicopter Co. 6775 Centinela Ave. Culver City, CA 90230-6370 (310)305-6562

Ten Cate Aerospace Inc. 5101 Blue Mound Rd. Fort Worth, TX 76106

Texstar 802 Ave. J East Grand Prairie, TX 75050-2552 (214)647-1366

OH-58

Bell Helicopter Textron Inc. 600 E Hurst Blvd. P.O. Box 482 Fort Worth, TX 76101-8020 (817)280-2011

Texstar, Inc. 802 Ave. J East Grand Prairie, TX 75050-2552 (214)647-1366

TH-67

Bell Helicopter Textron Inc. 600 E Hurst Blvd. P.O. Box 482 Fort Worth, TX 76101-8020 (817)280-2011

<u>UH-1</u>

PPG Industries, Inc. Aircraft Product Sales 1719 Highway 72 E P.O. Box 040004 Huntsville, AL 35804 (205)851-7001

Appendix A (Continued)

List of transparency manufacturers

<u>UH-60</u>

PPG Industries, Inc. 1 PPG PL Pittsburgh, PA 15272-0001 (412)434-3131

PPG 1719 Highway 72E P.O. Box 2200 Huntsville, AL 35804 (205)859-8500

Davis Aircraft Product Co. Inc. 1150 Walnut Avenue P.O. Box 525 Bohemia, NY 11716-2105 (516)563-1500

Appendix B

List of equipment manufacturers

EG&G Gamma Scientific Inc. 3777 Ruffin Rd. San Diego, CA 92123

Minolta Corporation 101 Williams Drive Ramsey, NJ 07446

Photo Research Division of Kollmorgen 9330 DeSoto Ave. P.O. Box 2192 Chatsworth, CA 91313-2192

Initial distribution

Commander, U.S. Army Natick Research,
Development and Engineering Center
ATTN: SATNC-MIL (Documents
Librarian)
Natick, MA 01760-5040

Chairman National Transportation Safety Board 800 Independence Avenue, S.W. Washington, DC 20594

Commander
10th Medical Laboratory
ATTN: Audiologist
APO New York 09180

Naval Air Development Center Technical Information Division Technical Support Detachment Warminster, PA 18974

Commanding Officer, Naval Medical Research and Development Command National Naval Medical Center Bethesda, MD 20814-5044

Deputy Director, Defense Research and Engineering ATTN: Military Assistant for Medical and Life Sciences Washington, DC 20301-3080

Commander, U.S. Army Research Institute of Environmental Medicine Natick, MA 01760

Library
Naval Submarine Medical Research Lab
Box 900, Naval Sub Base
Groton, CT 06349-5900

Executive Director, U.S. Army Human Research and Engineering Directorate ATTN: Technical Library Aberdeen Proving Ground, MD 21005

Commander Man-Machine Integration System Code 602 Naval Air Development Center Warminster, PA 18974

Commander Naval Air Development Center ATTN: Code 602-B Warminster, PA 18974

Commanding Officer Armstrong Laboratory Wright-Patterson Air Force Base, OH 45433-6573

Director Army Audiology and Speech Center Walter Reed Army Medical Center Washington, DC 20307-5001

Commander/Director
U.S. Army Combat Surveillance
and Target Acquisition Lab
ATTN: SFAE-IEW-JS
Fort Monmouth, NJ 07703-5305

Director
Federal Aviation Administration
FAA Technical Center
Atlantic City, NJ 08405

Director Walter Reed Army Institute of Research Washington, DC 20307-5100 IAF Liaison Officer for Safety USAF Safety Agency/SEFF 9750 Avenue G, SE Kirtland Air Force Base NM 87117-5671

Naval Aerospace Medical Institute Library Building 1953, Code 03L Pensacola, FL 32508-5600

Command Surgeon HQ USCENTCOM (CCSG) U.S. Central Command MacDill Air Force Base, FL 33608

Director
Directorate of Combat Developments
ATTN: ATZQ-CD
Building 515
Fort Rucker, AL 36362

U.S. Air Force Institute of Technology (AFIT/LDEE) Building 640, Area B Wright-Patterson Air Force Base, OH 45433

Henry L. Taylor Director, Institute of Aviation University of Illinois-Willard Airport Savoy, IL 61874

Chief, National Guard Bureau ATTN: NGB-ARS Arlington Hall Station 111 South George Mason Drive Arlington, VA 22204-1382

AAMRL/HEX Wright-Patterson Air Force Base, OH 45433 Commander
U.S. Army Aviation and Troop Command
ATTN: AMSAT-R-ES
4300 Goodfellow Bouvelard
St. Louis, MO 63120-1798

U.S. Army Aviation and Troop Command Library and Information Center Branch ATTN: AMSAV-DIL4300 Goodfellow BoulevardSt. Louis, MO 63120

Federal Aviation Administration Civil Aeromedical Institute Library AAM-400A P.O. Box 25082 Oklahoma City, OK 73125

Commander
U.S. Army Medical Department
and School
ATTN: Library
Fort Sam Houston, TX 78234

Commander
U.S. Army Institute of Surgical Research
ATTN: SGRD-USM
Fort Sam Houston, TX 78234-6200

Air University Library (AUL/LSE)
Maxwell Air Force Base, AL 36112

Product Manager Aviation Life Support Equipment ATTN: SFAE-AV-LSE 4300 Goodfellow Boulevard St. Louis, MO 63120-1798 Commander and Director
USAE Waterways Experiment Station
ATTN: CEWES-IM-MI-R,
CD Department
3909 Halls Ferry Road
Vicksburg, MS 39180-6199

Commanding Officer Naval Biodynamics Laboratory P.O. Box 24907 New Orleans, LA 70189-0407

Assistant Commandant
U.S. Army Field Artillery School
ATTN: Morris Swott Technical Library
Fort Sill, OK 73503-0312

Mr. Peter Seib Human Engineering Crew Station Box 266 Westland Helicopters Limited Yeovil, Somerset BA20 2YB UK

U.S. Army Dugway Proving Ground Technical Library, Building 5330 Dugway, UT 84022

U.S. Army Yuma Proving Ground Technical Library Yuma, AZ 85364

AFFTC Technical Library 6510 TW/TSTL Edwards Air Force Base, CA 93523-5000

Commander Code 3431 Naval Weapons Center China Lake, CA 93555 Aeromechanics Laboratory U.S. Army Research and Technical Labs Ames Research Center, M/S 215-1 Moffett Field, CA 94035

Sixth U.S. Army ATTN: SMA Presidio of San Francisco, CA 94129

Commander U.S. Army Aeromedical Center Fort Rucker, AL 36362

Strughold Aeromedical Library Document Service Section 2511 Kennedy Circle Brooks Air Force Base, TX 78235-5122

Dr. Diane Damos Department of Human Factors ISSM, USC Los Angeles, CA 90089-0021

U.S. Army White Sands
Missile Range
ATTN: STEWS-IM-ST
White Sands Missile Range, NM 88002

Director, Airworthiness Qualification Test Directorate (ATTC) ATTN: STEAT-AQ-O-TR (Tech Lib) 75 North Flightline Road Edwards Air Force Base, CA 93523-6100

Ms. Sandra G. Hart Ames Research Center MS 262-3 Moffett Field, CA 94035

Commander
USAMRMC
ATTN: SGRD-UMZ
Fort Detrick, Frederick, MD 21702-5009

Commander
U.S. Army Health Services Command
ATTN: HSOP-SO
Fort Sam Houston, TX 78234-6000

U. S. Army Research Institute Aviation R&D Activity ATTN: PERI-IR Fort Rucker, AL 36362

Commander U.S. Army Safety Center Fort Rucker, AL 36362

U.S. Army Aircraft Development Test Activity ATTN: STEBG-MP-P Cairns Army Air Field Fort Rucker, AL 36362

Commander
USAMRMC
ATTN: SGRD-PLC (COL R. Gifford)
Fort Detrick, Frederick, MD 21702

TRADOC Aviation LO Unit 21551, Box A-209-A APO AE 09777

Netherlands Army Liaison Office Building 602 Fort Rucker, AL 36362

British Army Liaison Office Building 602 Fort Rucker, AL 36362

Italian Army Liaison Office Building 602 Fort Rucker, AL 36362 Directorate of Training Development Building 502 Fort Rucker, AL 36362

Chief USAHEL/USAAVNC Field Office P. O. Box 716 Fort Rucker, AL 36362-5349

Commander, U.S. Army Aviation Center and Fort Rucker ATTN: ATZQ-CG Fort Rucker, AL 36362

Dr. Sehchang Hah
Dept. of Behavior Sciences and
Leadership, Building 601, Room 281
U. S. Military Academy
West Point, NY 10996-1784

Canadian Army Liaison Office Building 602 Fort Rucker, AL 36362

German Army Liaison Office Building 602 Fort Rucker, AL 36362

French Army Liaison Office USAAVNC (Building 602) Fort Rucker, AL 36362-5021

Australian Army Liaison Office Building 602 Fort Rucker, AL 36362

Dr. Garrison Rapmund 6 Burning Tree Court Bethesda, MD 20817

Commandant, Royal Air Force Institute of Aviation Medicine Farnborough, Hampshire GU14 6SZ UK Defense Technical Information Cameron Station, Building 5 Alexandra, VA 22304-6145

Commander, U.S. Army Foreign Science and Technology Center AIFRTA (Davis) 220 7th Street, NE Charlottesville, VA 22901-5396

Commander
Applied Technology Laboratory
USARTL-ATCOM
ATTN: Library, Building 401
Fort Eustis, VA 23604

Commander, U.S. Air Force
Development Test Center
101 West D Avenue, Suite 117
Eglin Air Force Base, FL 32542-5495

Aviation Medicine Clinic TMC #22, SAAF Fort Bragg, NC 28305

Dr. H. Dix Christensen Bio-Medical Science Building, Room 753 Post Office Box 26901 Oklahoma City, OK 73190

Commander, U.S. Army Missile
Command
Redstone Scientific Information Center
ATTN: AMSMI-RD-CS-R
/ILL Documents
Redstone Arsenal, AL 35898

Aerospace Medicine Team HQ ACC/SGST3 162 Dodd Boulevard, Suite 100 Langley Air Force Base, VA 23665-1995 U.S. Army Research and Technology Laboratories (AVSCOM) Propulsion Laboratory MS 302-2 NASA Lewis Research Center Cleveland, OH 44135

Commander
USAMRMC
ATTN: SGRD-ZC (COL John F. Glenn)
Fort Detrick, Frederick, MD 21702-5012

Dr. Eugene S. Channing 166 Baughman's Lane Frederick, MD 21702-4083

U.S. Army Medical Department and School USAMRDALC Liaison ATTN: HSMC-FR Fort Sam Houston, TX 78234

NVESD AMSEL-RD-NV-ASID-PST (Attn: Trang Bui) 10221 Burbeck Road Fort Belvior, VA 22060-5806

CA Av Med HQ DAAC Middle Wallop Stockbridge, Hants S020 8DY UK

Dr. Christine Schlichting Behavioral Sciences Department Box 900, NAVUBASE NLON Groton, CT 06349-5900

Commander Aviation Applied Technology Directorate ATTN: AMSAT-R-TV Fort Eustis, VA 23604-5577 COL Yehezkel G. Caine, MD Surgeon General, Israel Air Force Aeromedical Center Library P. O. Box 02166 I.D.F. Israel

HQ ACC/DOHP 205 Dodd Boulevard, Suite 101 Langley Air Force Base, VA 23665-2789

41st Rescue Squadron 41st RQS/SG 940 Range Road Patrick Air Force Base, FL 32925-5001

48th Rescue Squadron 48th RQS/SG 801 Dezonia Road Holloman Air Force Base, NM 88330-7715

HQ, AFOMA ATTN: SGPA (Aerospace Medicine) Bolling Air Force Base, Washington, DC 20332-6128

ARNG Readiness Center ATTN: NGB-AVN-OP Arlington Hall Station 111 South George Mason Drive Arlington, VA 22204-1382

35th Fighter Wing 35th FW/SG PSC 1013 APO AE 09725-2055

66th Rescue Squadron 66th RQS/SG 4345 Tyndall Avenue Nellis Air Force Base, NV 89191-6076 71st Rescue Squadron 71st RQS/SG 1139 Redstone Road Patrick Air Force Base, FL 32925-5000

Director
Aviation Research, Development
and Engineering Center
ATTN: AMSAT-R-Z
4300 Goodfellow Boulevard
St. Louis, MO 63120-1798

Commander
USAMRMC
ATTN: SGRD-ZB (COL C. Fred Tyner)
Fort Detrick, Frederick, MD 21702-5012

Commandant
U.S. Army Command and General Staff
College
ATTN: ATZL-SWS-L
Fort Levenworth, KS 66027-6900

ARNG Readiness Center ATTN: NGB-AVN-OP Arlington Hall Station 111 South George Mason Drive Arlington, VA 22204-1382

Director Army Personnel Research Establishment Farnborough, Hants GU14 6SZ UK

Dr. A. Kornfield 895 Head Street San Francisco, CA 94132-2813

ARNG Readiness Center AATN: NGB-AVN-OP Arlington Hall Station 111 South George Mason Drive Arlington, VA 22204-1382 Commander, U.S. Army Test and Evaluation Command Directorate for Test and Evaluation ATTN: AMSTE-TA-M (Human Factors Group) Aberdeen Proving Ground, MD 21005-5055

Naval Air Systems Command Technical Air Library 950D Room 278, Jefferson Plaza II Department of the Navy Washington, DC 20361

Director
U.S. Army Ballistic
Research Laboratory
ATTN: DRXBR-OD-ST Tech Reports
Aberdeen Proving Ground, MD 21005

Commander
U.S. Army Medical Research
Institute of Chemical Defense
ATTN: SGRD-UV-AO
Aberdeen Proving Ground,
MD 21010-5425

Commander USAMRMC ATTN: SGRD-RMS Fort Detrick, Frederick, MD 21702-5012

HQ DA (DASG-PSP-O) 5109 Leesburg Pike Falls Church, VA 22041-3258

Harry Diamond Laboratories ATTN: Technical Information Branch 2800 Powder Mill Road Adelphi, MD 20783-1197 U.S. Army Materiel Systems
Analysis Agency
ATTN: AMXSY-PA (Reports Processing)
Aberdeen Proving Ground
MD 21005-5071

U.S. Army Ordnance Centerand School LibrarySimpson Hall, Building 3071Aberdeen Proving Ground, MD 21005

U.S. Army Environmental
Hygiene Agency
ATTN: HSHB-MO-A
Aberdeen Proving Ground, MD 21010

Technical Library Chemical Research and Development Center Aberdeen Proving Ground, MD 21010-5423

Commander
U.S. Army Medical Research
Institute of Infectious Disease
ATTN: SGRD-UIZ-C
Fort Detrick, Frederick, MD 21702

Director, Biological Sciences Division Office of Naval Research 600 North Quincy Street Arlington, VA 22217

Commandant
U.S. Army Aviation
Logistics School ATTN: ATSQ-TDN
Fort Eustis, VA 23604

Headquarters (ATMD)
U.S. Army Training
and Doctrine Command
ATTN: ATBO-M
Fort Monroe, VA 23651

Cdr, PERSCOM ATTN: TAPC-PLA 200 Stovall Street, Rm 3N25 Alexandria, VA 22332-0413 HQ, AFOMA ATTN; SGPA (Aerospace Medicine) Bolling Air Force Base, Washington, DC 20332-6188